



## Pressure/torque conversion chart

Tool model: VERSA-20

Pressure		Torque		Pressure
psi	ft.-lbs	N-m		bar
1500	2148	4314		104
1600	2293	4601		110
1800	2582	5176		124
<b>2000</b>	<b>2871</b>	<b>5750</b>		<b>138</b>
2200	3164	6327		152
2400	3457	6901		165
2600	3751	7476		179
2800	4044	8051		193
<b>3000</b>	<b>4337</b>	<b>8627</b>		<b>207</b>
3200	4635	9202		220
3400	4933	9777		234
3600	5231	10351		248
3800	5529	10927		262
<b>4000</b>	<b>5827</b>	<b>11502</b>		<b>276</b>
4200	6127	12077		290
4400	6426	12652		303
4600	6725	13228		317
4800	7024	13803		331
<b>5000</b>	<b>7323</b>	<b>14377</b>		<b>345</b>
5200	7622	14952		358
5400	7922	15528		372
5600	8222	16103		386
5800	8521	16678		400
<b>6000</b>	<b>8821</b>	<b>17253</b>		<b>414</b>
6200	9121	17829		427
6400	9420	18404		441
6600	9720	18978		455
6800	10020	19553		468
<b>7000</b>	<b>10319</b>	<b>20129</b>		<b>482</b>
7200	10620	20704		496
7400	10921	21279		510
7600	11222	21854		524
7800	11523	22430		538
<b>8000</b>	<b>11824</b>	<b>23005</b>		<b>552</b>
8200	12123	23579		565
8400	12421	24154		579
8600	12720	24730		593
8800	13019	25305		607
<b>9000</b>	<b>13318</b>	<b>25880</b>		<b>620</b>
9200	13621	26455		634
9400	13924	27031		648
9600	14226	27605		662
9800	14529	28180		676
<b>10000</b>	<b>14832</b>	<b>28755</b>		<b>690</b>